	Туре	Hits	Search Text	DBs
1	BRS	18	"4,585,284"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
2	BRS	37	"4,857,002"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
3	BRS	14	"4,952,758"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
4	BRS	8	"5,587,685"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
5	BRS	36	"5,440,162"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
6	BRS	13	"5,155,648"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
7	BRS	11	"4,900,951"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
8	BRS	1623	hot same plugging	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
9	BRS	0	hot same plugging same communincation	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
10	BRS	41	hot same plugging same communication	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
11	BRS	323	hot same plug same communication	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
12	BRS	11	hot same plug same connector	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
13	BRS	1711	361/212	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
14	BRS	690	hot same (plug plugging) same connector	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
15	BRS	2	hot same (plug plugging) same connector same sliding same pir	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors	Ref #
1	2002/09/20 11:40				S1
2	2002/09/19 16:50				S2
3	2002/09/19 16:53				s3
4	2002/09/19 16:53				S 4
5	2002/09/19 16:54				S5
6	2002/09/19 16:54				S6
7	2002/09/19 17:07				s7
8	2002/09/19 17:07		·		S8
9	2002/09/19 17:08				S9
10	2002/09/19 17:15				S10
11	2002/09/19 17:15				S11
12	2002/09/19 17:26				S12
13	2002/09/19 17:27				S13
14	2002/09/20 09:23				S14
15	2002/09/20 .09:25				S15

	Туре	Hits	Search Text	DBs
16	BRS	0	hot same (plug plugging) same connector same sliiding adj contact	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
17	BRS	0	hot same (plug plugging) same connector same sliiding same contact	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
18	BRS	87	hot same (plug plugging) same connector same pin	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
19	BRS	4	hot same (plug plugging) same connector same (ground grounding) adj pin	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
20	BRS	0	"6,374,318" and (ground gounding) adj pin	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
21	BRS	1	"6,374,318" and (ground grounding) adj pin	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
22	BRS	5	hot same (plug plugging) same communication same connector same pin	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
23	BRS	0	hot same (plug plugging) same communication same connector same RC	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
24	BRS	1	hot same (plug plugging) same connector same RC	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
25	BRS	94	hot same (plug plugging swap) same connector same pin	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
26	BRS	6	hot same (plug plugging swap) same connector same (ground grounding) adj pin	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
27	BRS	15	("3795771" "4727244" "4853555" "4866515" "4896209" "4897714" "5123015" "5203004" "5404567" "5463261" "5473499" "5557541" "5568484" "5586937" "5636347").PN.	USPAT

	Time Stamp	Comments	Error Definition	Errors	Ref #
16	2002/09/20 09:26				S16
17	2002/09/20 10:37				S17
18	2002/09/20 10:26				S18
19	2002/09/20 09:47				S19
20	2002/09/20 09:47				S20
21	2002/09/20 09:47				S21
22	2002/09/20 09:57				S22
23	2002/09/20 09:57				S23
24	2002/09/20 09:57				S24
25	2002/09/20 10:26				S25
26	2002/09/20 10:37				S26
27	2002/09/20 10:29				S27

	Туре	Hits	Search Text	DBs
28	BRS	15	("3795771" "4727244" "4853555" "4866515" "4896209" "4897714" "5123015" "5203004" "5404567" "5463261" "5473499" "5557541" "5568484" "5586937" "5636347").PN.	USPAT
29	BRS	69	"5796185".URPN.	USPAT
30	BRS	436	hot same (plug plugging swap) same (filter filtering RC)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
31	BRS	17	hot same (plug plugging swap) same (filter filtering RC) same connector	US-PGPUB; USPAT;
32	BRS	36	"5,440,162"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
33	BRS	4	"5,440,162" and filter	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
34	BRS	14	("4821096" "4855647" "4900951" "5155648" "5243232" "5347185" "5392186" "5438213" "5440162" "5504362" "5508548" "5587685" "5744842" "5754074").PN.	USPAT
35	BRS	3311	connector same magnet	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
36	BRS	1	connector same magnet same reed same hot same (plug plugging)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
37	BRS	1	connector same magnet same reed same hot same (plug plugging swap swapping)	
38	BRS	222	connector same magnet same reed	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
39	BRS	14	same communication	DERWENT; IBM_TDB
40	BRS	0	connector same magnet same reed	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors	Ref #
28	2002/09/20 10:30				. S28
29	2002/09/20 10:35				S29
30	2002/09/20 10:38				s30
31	2002/09/20 10:52				S31
32	2002/09/20 10:53				S32
33	2002/09/20 10:53				S33
34	2002/09/20 10:55				S34
35	2002/09/20 11:40				S35
36	2002/09/20 11:43				S36
37	2002/09/20 11:43				S37
38	2002/09/20 12:00				S38
39	2002/09/20 11:44				S39
40	2002/09/20 11:52				S40

	Туре	Hits	Search Text	DBs
41	BRS	2	connector same magnet same reed same (protect protection)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
42	BRS	0	connector same magnet same reed same transient	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
43	BRS	0	connector same magnet same reed same surge	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
44	BRS	2	connector same magnet same reed same filter	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
45	BRS	2	connector same magnet same reed same bus	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
46	BRS	852	connector same (movable moving) adj (member pin)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
47	BRS	2142	connector same (movable moving) adj (member contact)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
48	BRS	727	connector same (movable moving) adj member	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
49	BRS	217964	connector same (movable moving) adj member same bias biasing	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
50	BRS	4 4	connector same (movable moving) adj member same (bias biasing)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
51	BRS	31	connector same (movable moving) adj member same pressing same member	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
52	BRS	9	"5,273,448"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
53	BRS	20	adi member same short	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
54	BRS	5	("3525056" "3529264" "3692966" "4429384" "4507627").PN.	USPAT
55	BRS	5	("3525056" "3529264" "3692966" "4429384" "4507627").PN.	USPAT
56	BRS	8		USPAT

	Time Stamp	Comments	Error Definition	Errors	Ref #
41	2002/09/20 11:54				S41
42	2002/09/20 11:54				S42
43	2002/09/20 11:54				S43
44	2002/09/20 11:55				S44
45	2002/09/20 13:32				S45
46	2002/09/20 13:34				S46
47	2002/09/20 13:34				S47
48	2002/09/20 13:36				S48
49	2002/09/20 13:36		·		S49
50	2002/09/20 14:06				S50
51	2002/09/20 14:26				S51
52	2002/09/20 14:24	,			S52
53	2002/09/20 15:16	i			S53
54	2002/09/20 14:54				S54
55	2002/09/20 14:54				S55
56	2002/09/20 14:56				S56

	Туре	Hits	Search Text	DBs
57	BRS	2	"6,410,869"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
58	BRS	14	("3553395" "3665495" "3697709" "3936782" "4157461" "4295054" "4423336" "4882554" "5233501" "5648745" "5721449" "5898239" "5909154" "5914467").PN.	USPAT
59	BRS	1954	361/58	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
60	BRS	2	"6,355,991"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
61	BRS	40	"5,530,302"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
62	BRS	23	"5,530,302" and communication	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
63	BRS	10	"5,659,888"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
64	BRS	1754	361/212	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
65	BRS	2021	361/58	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
66	BRS	239	439/924.1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
67	BRS	1658	439/188	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
68	BRS	828	200/51.1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
69	BRS	363	hot adj plugging and connector	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
70	BRS	20	hot adj plugging and connector and clock adj line	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB

	Time Stamp	Comments	Error Definition	Errors	Ref #
57	2002/09/20 15:16		:		S57
58	2002/09/20 15:17				S58
59	2002/09/20 16:05				S59
60	2002/09/24 10:01				S60
61	2002/09/24 10:57				S61
62	2002/09/24 11:10				S62
63	2002/09/24 11:10				S63
64	2003/03/26 10:38	,			S64
65	2003/03/26 12:40				S65
66	2003/03/26 15:31			·	S66
67	2003/03/27 11:27				S67
68	2003/03/27 14:27				S68
69	2003/11/16 13:28	_	,		S69
70	2003/11/16 13:28				s70

	Туре	Hits	Search Text	DBs
71	BRS	72	hot adj plugging and connector and clock and signal adj (line contact terminal)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
72	BRS	208450	hot adj plugging and connector and clock (line contact terminal) and signal adj (line contact terminal)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
73	BRS	14	hot adj plugging and connector and clock adj (line contact terminal) and signal adj (line contact terminal)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
74	BRS		hot adj plugging and connector and clock adj (line contact terminal) and signal adj (line contact terminal) same bidirectional	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
75	BRS	13	"5,787,298"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB
76	BRS	2001	361/212	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT
77	BRS	2521	361/58	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT
78	BRS	287	439/924.1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT
79	BRS	2097	439/188	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT
80	BRS	1139	200/51.1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT

	Time Stamp	Comments	Error Definition	Errors	Ref #
71	2003/11/16 13:29				S71
72	2003/11/16 13:29				s72
73	2003/11/16 13:31				s73
74	2003/11/16 13:31				S74
75	2003/11/16 14:36	١			S75
76	2004/12/15 11:09				s76
77	2004/12/15 11:51				s77
78	2004/12/15 14:47				S78
79	2004/12/15 15:20	×			S79
80	2004/12/15 16:41	V			S80